ED_001709_00001181-00001

SAMPLE CONTROL LOG

amec
foster
wheeler

Project Name: Leviathan Mine RI/FS, Alpine County, CA	Task Name	e: Rive	r Ranch	Deep C	anal s	amolha.	\
Project & Task No.: 6013 091150, 110R. 114A	Crew:	Joe (Sonzales	, Kab	Bon	Hen	
			-	,	7	1	

11 "		Sample	Sample ID	Sampling		Sample Collector	Sample Depth	Code ⁴	MS/ MSD collected?	•	Lab ⁷	Date Sent
Location ¹	Area ²	Matrix ³		Date	Time	Initials	(units)	Method ⁵	1	Additional Notes	Lab	to Lab
SRS	GA		58507271705	2422/12	1400	ゴム	. A			EPA PE Sample	ALS	7/27/17
3127	77/5			7 (-4)(7	1,127	70	NA			metals except cr		
SRS	C C A		486-227-17-6	- 11-	1.6 (** 20)					EPA PE sample	ALS	7/27/17
3128	55A		58507271706	+(4)+	1428	5	NA			metals except com		-
SRS	C Z A			1112		75				EPA PE sample	ALS	7/27/17
3129	אדר		58507271707	TICUIT	1501	7	NA			metals except case	,	-
SRS	$C \leq \lambda$			- l(رسيد	_			EPA PE sample	ALS	7 (27/17
3130	フフハ		58507271708	+12417	1505	17	NA			metals except cate		-
			168 V2									
				717								

- 1. Sample Locations include: EB or FB for blanks, Monitoring Well ID, Boring ID, or other defined sampling location as directed in sampling planning documents.
- 2. If applicable, study area examples are Aspen Creek Study Area (ACSA), Leviathan Creek Study Area (LCSA), Pit Study Area (PSA), Downstream Study Area (DSA), Reference Study Area (RSA) or Supplemental Study Area (SSA).
- 3. Sample matrices defined in project planning documents.
- 4. Sample Code includes: Normal Environmental (NE), Field Duplicate (FD), Field Blank (FB), and Equipment Blank (EB)
- 5. Sampling methods include: Grab, Composite (Comp), Incremental (Incr), or Autosampler (Auto)
- 6. Include notes such as: locations of blanks, parent sample identification for field duplicates, sample location details, handling notes, chain-of-custody remarks, etc.
- 7. Lab performing sample analyses identified in project planning documents.

Amec Foster Wheeler	Environment	and Infrastructure,	Inc
Form checked by	(initials/date)	GB VOVIT	

Recipient Copy

CHAIN-OF-CUSTODY RECORD

COC No.

14043

Order Number: CB013480

Date Shipped: 7/19/2017

AirBill No(s):

560847661979

From:

QATS LABORATORY

2700 CHANDLER AVENUE, BLDG, B

LAS VEGAS, NV 89120 PHONE: 1-702-895-8712 To: **BRITT JONES**

AMECFW

931 BOLLEN CIRCLE

GARDNERVILLE

NV 89460

FAX: 1-702-795-8210 916-612-6237

FAX; I-	-702-795-8210			916-612-6237			
Sample ID	Sigma ID	Qty	Description/	Remarks	→ Catalog	jue Numb	er
SRS3127	SR0897	1	METALS IN SO	IL PES	s	R-PES	
SRS3128	SR0897	1	METALS IN SO	IL PES	s	R-PES	
SRS3129	SR0897	1	METALS IN SO	IL PES	S	R-PES	
SRS3130	SR0897	1	METALS IN SO	IL PES	S	R-PES	
			SUPERFUND SI	TE NAME: LEVIATHAN I	MINE	·	
Please use the Instructions use listed above.	enclosed Sample the Sample Pre	e Prepar paration	ation Instructions. If ca Instructions with catalo	talogue number(s) are listed gue number(s) matching th	at the top of the Sample Prepe e catalogue number(s) of each	aration of the sample	es
Relinquished by: (Signature) Custody Seal(s): Present/Absent	Pin)	Date/Time YOD Remarks:	Received by: (Signature)	fance .	Date/Time	/1:30
Relinquished by:			Date/Time	Received by:		Date/Time	

(Signature)

Report No. 00, 9/11/2014

(Signature)

SMP Version 3.3